SECONDLY WILLIAMS

## OFFICE MINIORANDOM

**70:** 

Chief. D/C

6 June 1952

PROM:

I/W

25X1A

25X1A Request for Information 44

25X1A6a

25X1A9a

25X1A9a

25X1A

25X1A

Numerous reports received here have shewn that two principal AFF repair centers in Germany are the former German sailread car repair shops in Kirchmösser and the Krupp-Grason - Bucksm-Wolff complex in Magdeburg.

## RECEIPTS

The following information would be most helpful concerning these installations and the Soviet AFV holdings in SovZone Germany

- 1. Which parts are cleased, repaired and put back into the tank and which parts are discarded in favor of new parts? What wear shows on various parts?
- 2. How many tanks go through the process in a given period of time and how long does it take each tank to go through the process?
- 3. What units or what percentage of the total armored forces in Sevione Germany does each of these particular installations service?
- 4. Can your source estimate via question 3 that the annual rate of depletion for AFV's in Sovice is?
- 5. Are there any modifications, changes, or variations incorporated . isto the repaired tank, such as, ripped armor, stabilisation, special sights, infra-red or sighting devices, etc.?
- 6. The decides which tanks go through the repair process and which tanks go to the scrap pile and how is that decision reached?
- 7. What machine tools, with details, and metallurgical equipment. with details, are available; what kind of outting tools, f.e., tungsten carbide, high speed steel, are utilisel?
- 8. What detailed information concerning the ordnance over-haul shop can be secured?

DEGREE OF MEED: Standard

TARGET DATE

ORIGINATOR

15 July 52

COORDINATION :

25X1A9a

25X1A9a



18 June 18 18